


# Knoydart Estate - Phase 1 Peatland Restoration

Restoration Overview Map



### Legend

- Knoydart Estate Boundary
- Phase 1 - Restoration footprint
- Work Zones**
  - 1
  - 2
  - 3
- Access Routes**
  - Existing Roads
  - Existing Tracks
  - Actively Eroding: Hagg/Gully
  - Artificial Drains
- National Record of the Historic Environment Features
- Rig and Furrow
- Waterlines
- 2022 Walkover Survey - Archaeology Sites

Produced by: Zulu Ecosystems  
Date: 2025-09-24  
Map Scale: 1:31561